



00257066

Form 9-  
Dec. 1973

RECEIVED

OCT 14 1982

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

COLD OIL & GAS CONS. COMM.

5. LEASE  
D-028963

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
McCallum Unit

8. FARM OR LEASE NAME

9. WELL NO.  
55

10. FIELD OR WILDCAT NAME  
McCallum-Pierre

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Section 2, T9N, R79W

12. COUNTY OR PARISH 13. STATE  
Jackson | Colorado

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
8,198' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
Conoco Inc.

3. ADDRESS OF OPERATOR  
907 Rancho Road Casper, Wyoming 82601

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1670' FNL, 2270' FWL (SE/NW)  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) Status Report <input type="checkbox"/>	<input type="checkbox"/>

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Surface pipe was set July 9, 1972, at which time drilling operations were suspended. We wish to retain the well in this status pending continued further engineering and geological evaluation.

DVR
BP
WFM
JAM
JHE
REB
SMY

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct  
SIGNED C. Thompson TITLE Adm. Supervisor DATE October 7, 1982

(This space for Federal or State office use)  
APPROVED BY [Signature] TITLE DIRECTOR DATE OCT 21 1982  
CONDITIONS OF APPROVAL, IF ANY: O & G Cons. Comm.

MMS(3) COGCC(2) File