



RECEIVED

OCT 10 1980

COLO. OIL & GAS CONS. COMM.

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well [X] gas well [] other []
2. NAME OF OPERATOR Conoco Inc.
3. ADDRESS OF OPERATOR 907 Rancho Road, Casper, Wyoming 82601
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1670' FNL, 2270' FWL SE/NW

5. LEASE D-028963
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME McCallum Unit
8. FARM OR LEASE NAME
9. WELL NO. 55
10. FIELD OR WILDCAT NAME McCallum-Pierre
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 2, T9N, R79W
12. COUNTY OR PARISH Jackson 13. STATE Colorado
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD) 8198' GR

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF [] FRACTURE TREAT [] SHOOT OR ACIDIZE [] REPAIR WELL [] PULL OR ALTER CASING [] MULTIPLE COMPLETE [] CHANGE ZONES [] ABANDON* [] (other) Status Report
SUBSEQUENT REPORT OF: [] [] [] [] [] [] [] [] [] []

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Surface pipe was set July 9, 1972, at which time drilling operations were suspended. We wish to retain the well in this status pending continued further engineering and geological evaluation.

Table with names: DVR, FJP, HHM, JAM, JJD, RLS, CGM

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Supervisor DATE 10/7/80

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE DIRECTOR DATE OCT 15 1980

*See Instructions on Reverse Side

RECEIVED
OCT 10 1986

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

REQUEST	DATE	BY	SENT	BY
6 1st	8-27-86	TS		
2nd				
3rd				
4th				
FILE CLOSED				
Form 4				
✓ Form 5	X front + back			
Cmt Verif	Form 5 not required			
Form 10	hole drilled to 60'			
Logs	only + P + A.			
Plat				Qm
Other				

✓	500
✓	510
✓	520
✓	530
✓	540
✓	550
✓	560
✓	570
✓	580
✓	590
✓	600

OCT 11 1986