

Interim Reclamation and Stormwater Inspection

February 3, 2026

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: BELL #3-16A

Well Name: CHARLES C BELL UNIT #2

Inspection Document #: 718601349

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CHARLES C BELL UNIT #2
Location ID: BELL #3-16A



Photo 1. Looking west across the location. The well is in a heavily grazed cattle pen. The location size is appropriate. Weeds are controlled at the time of inspection.



Photo 2. Looking south at the pumpjack.



Inspection Photos
Location Name: CHARLES C BELL UNIT #2
Location ID: BELL #3-16A



Photo 3. Photo taken at the transformers and control station to the west of the pumpjack. A signal pole is broken off and wedged in the fencing.



Photo 4. The signal pole cable is disconnected.

Inspection Photos
Location Name: CHARLES C BELL UNIT #2
Location ID: BELL #3-16A



Photo 5. Meter has power.



Photo 6. Looking north towards the pumpjack.

