

# Final Reclamation Inspection

January 22, 2026

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 430547

Inspection Document #: 718801305

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BDE Facility/27NW  
Location ID: 430547



**Photo 1.** Photo taken of the tank battery location, facing south. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



**Photo 2.** Photo taken of the tank battery location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: BDE Facility/27NW  
Location ID: 430547



**Photo 3.** Photo taken of the tank battery location, facing north. See comments under Photo 1.



**Photo 4.** Photo taken of the tank battery location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: BDE Facility/27NW  
Location ID: 430547



**Photo 5.** Photo of ground cover at the location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*) and russian thistle (*Bassia scoparia*).



**Photo 6.** Photo taken of the reference area to the location, east of the location, facing southwest. Photo illustrates weedy annual vegetation.