

Final Reclamation Inspection

January 22, 2026

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 430544

Inspection Document #: 718801303

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BDE Multi Well Pad 27NW
Location ID: 430544



Photo 1. Photo taken of the multi-well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. The location is dominated by weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 2. Photo taken of the multi-well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: BDE Multi Well Pad 27NW
Location ID: 430544



Photo 3. Photo taken of the multi-well location, facing south.
See comments under Photo 1.



Photo 4. Photo taken of the multi-well location, facing west.
See comments under Photo 1.

Inspection Photos
Location Name: BDE Multi Well Pad 27NW
Location ID: 430544



Photo 5. Photo of ground cover at the location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 6. Photo taken of the reference area to the location, west of the location, facing southwest. Photo illustrates weedy annual vegetation.