

# Final Reclamation Inspection

January 30, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 309764

Inspection Document #: 718801321

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PEDRO STATE G #36-18  
Location ID: 309764



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows from seeding, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: PEDRO STATE G #36-18  
Location ID: 309764



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: PEDRO STATE G #36-18  
Location ID: 309764



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates perennial grass and drill rows from seeding.



**Photo 6.** Photo taken of the access road to the location, facing west, towards the location. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.

Inspection Photos  
Location Name: PEDRO STATE G #36-18  
Location ID: 309764



**Photo 7.** Photo taken of the access road to the well location, facing northwest. See comments under Photo 6.



**Photo 8.** Photo taken of the tank battery location, facing southwest. Photo illustrates that final reclamation activities have not taken place at the tank battery. A porta potty was observed at the location tipped over.

Inspection Photos  
Location Name: PEDRO STATE G #36-18  
Location ID: 309764



**Photo 9.** Photo taken of the tank battery location, facing southeast. See comments under Photo 8.



**Photo 10.** Photo taken of the reference area to the location, north of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.

