

# Final Reclamation Inspection

January 30, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 305340

Inspection Document #: 718801311

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GERRITY STATE G #36-17  
Location ID: 305340



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place and perennial grass vegetation is establishing.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: GERRITY STATE G #36-17  
Location ID: 305340



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: GERRITY STATE G #36-17  
Location ID: 305340



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



**Photo 6.** Photo taken of the access road to the location, facing northwest, towards the location. Photo illustrates bare ground and weedy annual vegetation, including kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*).

Inspection Photos  
Location Name: GERRITY STATE G #36-17  
Location ID: 305340



**Photo 7.** Photo taken of ground cover along the access road to the location. Photo illustrates bare ground remains along the access road.



**Photo 8.** Photo taken of the reference area to the location, northwest of the location, facing northwest. Photo illustrates perennial grass and weedy annual vegetation.

