

Final Reclamation Inspection

January 30, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 326693

Inspection Document #: 718801319

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GERRITY STATE G #36-07
Location ID: 326693



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows from seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: GERRITY STATE G #36-07
Location ID: 326693



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: GERRITY STATE G #36-07
Location ID: 326693



Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass and drill rows from seeding.



Photo 6. Photo taken of the access road to the location. Photo illustrates that the access road does not meet Rule 1004 standards as bare ground remains across the road.

Inspection Photos
Location Name: GERRITY STATE G #36-07
Location ID: 326693



Photo 7. Photo taken of the reference area to the location, northeast of the location, facing east. Photo illustrates perennial grass and weedy annual vegetation.

