

# Final Reclamation Inspection

January 30, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 326710

Inspection Document #: 718801331

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE R G #36-3  
Location ID: 326710



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: STATE R G #36-3  
Location ID: 326710



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: STATE R G #36-3  
Location ID: 326710



**Photo 5.** Photo taken of ground cover at the location. Photo illustrates drill rows from seeding and perennial grass.



**Photo 6.** Photo taken of the access road to the location. Photo illustrates that final reclamation does not meet Rule 1004 standards along the road as bare ground remains.

Inspection Photos  
Location Name: STATE R G #36-3  
Location ID: 326710



**Photo 7.** Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass and weedy annual vegetation.

