

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 231-34 Pad

Location ID: 324038



Photo # 8025 From entrance to location



Photo # 8026 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 231-34 Pad

Location ID: 324038



Photo # 8027 Location



Photo # 8028 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 231-34 Pad

Location ID: 324038




Photo # 8029 Location



Photo # 8030 Open ended piping on fire tube/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 231-34 Pad

Location ID: 324038



**Photo # 8031 Open ended piping on dehy still column
/wildlife hazard/available for entry by wildlife**

**Photo # 8032 Open ended piping on dehy still column
/wildlife hazard/available for entry by wildlife**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 231-34 Pad

Location ID: 324038



**Photo # 8033 Hole in separator roof/wildlife hazard
/available for entry by wildlife**



**Photo # 8034 Hole in separator roof/wildlife hazard
/available for entry by wildlife**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 231-34 Pad

Location ID: 324038



Photo # 8035 Open ended load line



Photo # 8036 Open ended load line