

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785



Photo 1 – Rods




Photo 2 – Unused Wellhead Part

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785




Photo 3 – Fence Paneling in disrepair

Photo 4 – Stained Soil and Tumbleweeds at Power Unit

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785



Photo 5 – Power Unit



Photo 6 – Separators

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785



Photo 7 – Gas Meters




Photo 8 – Unused parts

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785



Photo 9 – Nitrogen Tank

Photo 10 – Tank Battery

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785



Photo 11 – Tank Battery Signs

Photo 12 – Tank Battery