

# Inspection Photos

API:017-07380

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/2/2026

County: KIOWA




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial image facing east along the former access road.



## Inspection Photos



**Photo 2.** Drone aerial photo facing east toward the abandoned wellsite. The crop is not uniformly growing at the former wellsite.



## Inspection Photos



**Photo 3.** Drone aerial photo facing west toward the abandoned wellsite. The crop is not uniformly growing at the former wellsite.



## Inspection Photos



**Photo 4.** Drone aerial photo facing down at the location shows crop is not uniformly growing at the former wellsite.

