

No work has been completed since previously submitted SF27 document number 404434092 was submitted on 11/13/25, which has not yet been reviewed by ECMC. This form is being submitted to satisfy the Rule 913.e quarterly requirement. Excavation and soil sampling per approved SF27 document number 404123522 will occur in conjunction with the approved excavation and soil sampling for remediation project number 22996 at the same location. Murfin has prioritized the 3 Red Poll decommission remediation project numbers 38897, 39477, and 39421. Once work for those projects is nearing completion, the focus will turn to this project. Murfin anticipates this happening in 2Q26.