

Inspection Photos

API:061-06217

Operator: WESTERN OPERATING COMPANY

Inspection Date: 7/15/2025

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south at the location. The perennial vegetation has not re-established.



Inspection Photos



Photo 2. Facing southwest toward the location. The perennial vegetation has not re-established.



Inspection Photos



Photo 3. Center of the location facing west. This bare area is approximately 50'x50'.



Inspection Photos



Photo 4. Facing east at the location.



Inspection Photos



Photo 5. Facing south toward the undisturbed surrounding pasture.

