

Inspection Photos  
Location: Pyles, Bertha 2  
Spill Facility ID 483705 and 485862  
Remediation Project # 37449 and 34392



Photo 1 – Tank Battery Information

Photo 2 – Tank Battery

Inspection Photos  
Location: Pyles, Bertha 2  
Spill Facility ID 483705 and 485862  
Remediation Project # 37449 and 34392



**Photo 3 – Impacts to soils.**

**Photo 4 – Excavation**

Inspection Photos  
Location: Pyles, Bertha 2  
Spill Facility ID 483705 and 485862  
Remediation Project # 37449 and 34392



Photo 5 – Excavation

Photo 6 – Excavation

Inspection Photos  
Location: Pyles, Bertha 2  
Spill Facility ID 483705 and 485862  
Remediation Project # 37449 and 34392



Photo 7 – Excavation

Photo 8 – Excavation

Inspection Photos  
Location: Pyles, Bertha 2  
Spill Facility ID 483705 and 485862  
Remediation Project # 37449 and 34392



Photo 9 – Access for excavation

Photo 10 – Cattle panels along Count Road 58.5.