

Inspection Photos
Location: King Pyles # 4
Location ID 470688
Remediation Project # 21723



Photo 1 – Tank Battery Information

Photo 2 – Tank Battery open excavation

Inspection Photos
Location: King Pyles # 4
Location ID 470688
Remediation Project # 21723



Photo 3 – Impacts to soils.

Photo 4 – Battery

Inspection Photos
Location: King Pyles # 4
Location ID 470688
Remediation Project # 21723



Photo 5 – Battery

Photo 6 – Battery

Inspection Photos
Location: King Pyles # 4
Location ID 470688
Remediation Project # 21723



Photo 7 – Impacts to soil at tank base

Photo 8 – Low-lying area, impacts to soils

Inspection Photos
Location: King Pyles # 4
Location ID 470688
Remediation Project # 21723



Photo 9 – Impacts to soils