

Inspection Photos
Location: King Pyles # 4
Location ID: 470688
Spill ID 480894



Photo 1 –Facility Placard



Photo 2 – Tank Battery

Inspection Photos
Location: King Pyles # 4
Location ID: 470688
Spill ID 480894



Photo 3 – Heater Treater



Photo 4 – Remediation Excavation

Inspection Photos
Location: King Pyles # 4
Location ID: 470688
Spill ID 480894



Photo 5 – Tank Battery



Photo 6 – Unused Tanks removed



Inspection Photos
Location: King Pyles # 4
Location ID: 470688
Spill ID 480894



Photo 7 – Areas of impacted soils



Photo 8 – Areas of impacted soils

Inspection Photos
Location: King Pyles # 4
Location ID: 470688
Spill ID 480894



Photo 9 – Areas of impacted soils



Photo 10 – Areas of impacted soils