



ORAL APPROVAL TO PLUG AND ABANDON WELL

Operator Devon Corp. Representative Don Condi

Well No. BULCH#1-4 Located SW 1/4 SE 1/4 Sec. 4 Twp 9N Range 92W

Lease No. C-13833 Field \_\_\_\_\_ State Colorado

Unit Name and Required Depth Wildcat Base of fresh water sands \_\_\_\_\_

T.D. 8150 Size hole and Fill Per Sack \_\_\_\_\_ Mud Weight and Top 9.5 #/gal. \_\_\_\_\_

Casing Size	Set At	Top of Cement	To Be Pulled	Plugging Requirements		
				From	To	Sacks Cement
<u>10 3/4"</u>	<u>537'</u>	<u>Cement to Surf.</u>		<u>35 SX on surface + Mark.</u>		
				<u>400'</u>	<u>700'</u>	<u>TO COVER WATER SANDS</u>

Formation	Top	Base	Shows
<u>Wasatch</u>	<u>Surface</u>		
<u>Fort Union</u>	<u>3490'</u>		
<u>Lance</u>	<u>4700'</u>		
<u>Lewis shale</u>	<u>5685'</u>		
<u>Lewis ss</u>	<u>6190'</u>		
<u>Mesa Verde</u>	<u>7650'</u>		

	<u>3725'</u>	<u>3734'</u>	
	<u>3498'</u>	<u>3506'</u>	
<u>coal seams</u>	<u>3994'</u>	<u>4016'</u>	<u>logged to 7430'</u>
	<u>4020'</u>	<u>4030'</u>	

TOP OF FISH AT 4014'. LOST 2' Remarks  
 4100' OF DRILL PIPES & COLLARS. LEWIS ZONE TESTED GAVE 44 MCL FROM 6220'-623  
 DST'S, lost circulation zones, water zones, etc. LOST CIRC. IN COAL. BUT  
 WAS CONTROLLED. LEVEL HOLE & FENCE PITS. CLEAR  
 LOCATION & REHAB AS PER BLM SPECS  
 WILL USE CLASS 6 CEMENT + 2% CALCL + 4% Bentonite

Approved by [Signature] Date 1-28-81 Time 12:40 A.M.  
P.M.

cc: opn w: Condi of Approval  
 BLM, CRAIG w/ Condi of Approval  
 HSGS - VERNAL  
 MER CONTROL BOOK FILE [Signature]