

# Inspection Photos

API:063-06232

Operator: ANSCHUTZ CORPORATION\* THE

Inspection Date: 2/3/2026

County: KIT CARSON



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo shows fence posts remain around the location.



## Inspection Photos



**Photo 2.** Southeast corner facing northwest. Corner post remains.



## Inspection Photos



**Photo 3.** Northeast corner facing west. Corner post remains.



## Inspection Photos



**Photo 4.** Drone aerial photo facing south overlooking the location Uniform vegetation appear to be established..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 063-06232 | Date: 2/3/2026