

Action: Spill Samples & Screening


Remediation No.: 17696

Discovery Date: 07/27/2016

Spill Pt. Latitude: 40.378040 Longitude: -102.533600

Facility ID: 447096

Type: Produced Water



Name	Sample Date	Latitude	Longitude	Feet to Wellhead / SP
Background	1/19/2026 11:43:00 AM	40.377876	-102.533699	65
Sample #1	1/19/2026 11:37:00 AM	40.378058	-102.533501	28
Sample #2	1/19/2026 11:31:00 AM	40.378056	-102.533354	68



Name	Screen Type	Screen Date	Sq. Ft.
Screening Area	Visual	1/19/2026	800

Status	Type	Asset	US Feet	Start Lat	Start Lon	End Lat	End Lon
	Active	Produced Water	Flowline	885	40.378040	-102.533599	40.380467 -102.533633
	Active	Natural Gas	Offsite flowline	866	40.378040	-102.533601	40.380416 -102.533608