

Inspection Photos

API:063-06257

Operator: P O & G OPERATING LLC

Inspection Date: 2/3/2026

County: KIT CARSON



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. The electric utility needs to be removed. All tanks equipment must be removed..



Inspection Photos



Photo 2. Tank battery was not removed. All equipment should have been removed within 3 months of abandonment..



Inspection Photos



Photo 3. There is steel rods and electric utility that needs to be removed.



Inspection Photos



Photo 4. Photo taken during previous inspection shows E&P waste spill out onto the ground..

