

Inspection Photos

API:063-06271

Operator: P O & G OPERATING LLC

Inspection Date: 2/3/2026

County: KIT CARSON



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east at the location This bare area is approximately 120ft x 60ft. It appears there are impacted soils from a historical release.



Inspection Photos



Photo 2. Facing west at area with no vegetation.



Inspection Photos



Photo 3. It appear the historic spill may have spread into this drainage area.



Inspection Photos



Photo 4. Facing northeast toward the down gradient drainage area.

