

Inspection Photos

API: 063-06349

Operator: **H2E OPERATIONS LLC**

Inspection Date: 2/3/2025

County: KIT CARSON



Inspection Photos



Photo 1. Facing north at the beginning of the former access road. The cattleguard and perimeter fence have not been removed.



Inspection Photos



Photo 2. Facing east at the location . The perimeter fence remains around the location and is in disrepair.



Inspection Photos



Photo 3. Drone aerial photo facing northwest toward the location.



Inspection Photos



Photo 4. Drone aerial photo. Center of the location facing west.

