

# Inspection Photos

02/06/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334927

Inspection Doc: 719200799

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334927



**Photo 1:** Photos showing an overview of the location looking northwest and southeast, respectively. The northern and northwestern portions of the location appear to be progressing towards 1004 final reclamation requirements.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334927



**Photo 2:** Photos showing an overview of the southern/southeastern portions of the location looking north and south, respectively. These portions of the location are predominantly bare or populated by prickly Russian thistle, an undesirable annual plant species, and do not appear to be progressing towards 1004 final reclamation requirements.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334927



**Photo 3:** Photos showing an overview of the southern/southeastern portion of the location. These portions do not appear to be progressing towards 1004 final reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources