

Inspection Photos
Kinder Morgan Sand Canyon #11
API # 05-083-06684
Inspector Name: James Blair. Inspection Date: 02/06/2026
Inspection Doc #: 721100110




01. Well Sign.

Inspection Photos
Kinder Morgan Sand Canyon #11
API # 05-083-06684
Inspector Name: James Blair. Inspection Date: 02/06/2026
Inspection Doc #: 721100110



02: Well pad entrance looking south.

Inspection Photos
Kinder Morgan Sand Canyon #11
API # 05-083-06684
Inspector Name: James Blair. Inspection Date: 02/06/2026
Inspection Doc #: 721100110



03. Wellhead has been temporarily abandoned. Flow line segment from wellhead on left to valve where flow line goes underground to local gathering system has been removed.

Inspection Photos
Kinder Morgan Sand Canyon #11
API # 05-083-06684
Inspector Name: James Blair. Inspection Date: 02/06/2026
Inspection Doc #: 721100110



04. Bradenhead access beneath metal grating atop well cellar.

Inspection Photos
Kinder Morgan Sand Canyon #11
API # 05-083-06684
Inspector Name: James Blair. Inspection Date: 02/06/2026
Inspection Doc #: 721100110



05. Well pad overview photo. Site is clear of undesirable vegetation. OOSLAT marker on flow line.