


# QB ENERGY OPERATING LLC BENTLEY-67S95W 11NESE Facility # 324174



**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11NESE  
Facility # 324174**



**Hatch on back of north tank has severe rust.**



**Hatch on back of north tank has severe rust.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11NESE  
Facility # 324174**



**Middle tank hatch cover**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11NESE  
Facility # 324174**



**South tank hatch cover**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11NESE  
Facility # 324174**



**No sign seen at wellhead.**