

Inspection Photos

Location Name: George Norden Consolidation & George Norden West

Spill ID: 479923 & 487301



Backfilled excavation

Backfilled excavation



Inspection Photos

Location Name: George Norden Consolidation & George Norden West

Spill ID: 479923 & 487301



Scattered fencing

Scattered fencing



Inspection Photos
Location Name: George Norden Consolidation & George Norden West
Spill ID: 479923 & 487301



Pumpjack issues

Pumpjack issues

Inspection Photos

Location Name: George Norden Consolidation & George Norden West

Spill ID: 479923 & 487301



Pumpjack issues

Pumpjack issues

Inspection Photos
Location Name: George Norden Consolidation & George Norden West
Spill ID: 479923 & 487301



Pumpjack issues

