

Inspection Photos
Location Name: David Howard Flowline Release
Spill ID: 484274



Spill location

Spill location

Inspection Photos

Location Name: David Howard Flowline Release
Spill ID: 484274



Spill location

Inadequate signage



Inspection Photos
Location Name: David Howard Flowline Release
Spill ID: 484274



Inadequate signage

Spill location and trash