

# INSPECTION PHOTOS

Well: Golden Eagle 33-12

API #: 05-071-09487

INSPECTION DOC #: 716301950

Operator: OGRIS OPERATING LLC 10758

Inspection date: 2/10/2026

County: Las Animas



PHOTO 2: WELL SIGN



Network:Feb 10, 2026 at 11:01:12 AM MST  
Local:Feb 10, 2026 at 11:01:12 AM MST  
+37.124897,-104.898118  
Las Animas County

PHOTO 3: LOCATION.



**PHOTO 4: Vacuum pump observed on well without ECMC approval. Provide ECMC with documentation showing approval of use of vacuum pump. Ca date 2-27-2026.**



Network:Feb 10, 2026 at 11:03:13 AM MST  
Local:Feb 10, 2026 at 11:03:13 AM MST  
+37.124566,-104.898123  
Las Animas County

**PHOTO 5: Area of impacted soil near wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2-27-2026.**