

INSPECTION PHOTOS

Well: Golden Eagle 33-15

API #: 05-071-09480

INSPECTION DOC #: 716301957

Operator: OGRIS OPERATING LLC 10758

Inspection date: 2/10/2026

County: Las Animas



OGRIS
OPERATING, LLC

719-497-0446
or EMERGENCY 911

WDID 1912566
PERMIT 74293

GOLDEN EAGLE 33-15

API# 05-071-09480

SE/SW 33-33S-67W

NAD 83

LAT. 37.122151

LONG. -104.891526

API# 05-071-09480

Network: Feb 10, 2026 at 1:09:11 PM MST
Local: Feb 10, 2026 at 1:09:11 PM MST
+37.122013, -104.891559
Las Animas County

PHOTO 2: WELL SIGN



PHOTO 3: LOCATION.



Network:Feb 10, 2026 at 1:08:34 PM MST
Local:Feb 10, 2026 at 1:08:34 PM MST
+37.122296,-104.891484
Las Animas County

PHOTO 4: Vacuum pump observed on well without ECMC approval. Provide ECMC with documentation showing approval of use of vacuum pump. Ca date 2/23/2026.



PHOTO 5: area of impacted soil near wellhead appears to be from leaking hydraulic hose. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



PHOTO 6: area of impacted soil near compressor skid. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. ca date 2/23/2026.



PHOTO 7: area of impacted soil near prime mover engine skid. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



PHOTO 8: trash on south side of location. **Remove all trash on and around location per rule 606. ca date 2/23/2026.**



Network:Feb 10, 2026 at 1:13:28 PM MST
Local:Feb 10, 2026 at 1:13:28 PM MST
+37.122181,-104.891479
Las Animas County

PHOTO 9: trash near compressor skid. Remove all trash on and around location per rule 606. ca date 2/23/2026.



Network:Feb 10, 2026 at 1:12:59 PM MST
Local:Feb 10, 2026 at 1:12:59 PM MST
+37.121974,-104.891489
Las Animas County

PHOTO 10: no guy line marker on southeast anchor. **Install proper guy line markers per Rule 1003.a. ca date 2/23/2026.**



PHOTO 12: OILY WASTE IN COMPRESSOR SKID WITHOUT WILDLIFE PROTECTION SCREENS OR COVERS. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. IMMEDIATE ACTION IS REQUIRED. CA DATE 2/11/2026.



Network:Feb 10, 2026 at 1:11:04 PM MST
Local:Feb 10, 2026 at 1:11:04 PM MST
+37.122188,-104.891553
Las Animas County

PHOTO 11: OILY WASTE IN PRIME MOVER ENGINE SKID WITHOUT WILDLIFE PROTECTION SCREENS OR COVERS. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. IMMEDIATE ACTION IS REQUIRED. CA DATE 2/11/2026.