

INSPECTION PHOTOS

Well: Apache Canyon 04-01

API #: 05-071-09633

INSPECTION DOC #: 716301959

Operator: OGRIS OPERATING LLC 10758

Inspection date: 2/10/2026

County: Las Animas



OGRIS
OPERATING, LLC

719-497-0446
or EMERGENCY 911

WDID 1912593
PERMIT 74305

APACHE CANYON 04-01

API# 05-071-09633

NE/NE 04-34S-67W

NAD 83

LAT. 37.119453

LONG. -104.888513

API# 05-071-09633

Network: Feb 10, 2026 at 1:58:47 PM MST
Local: Feb 10, 2026 at 1:58:47 PM MST
+37.119538, -104.888404
Las Animas County

PHOTO 2: WELL SIGN



PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: Area of impacted soil near wellhead appears to be from leaking hydraulic hose. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



PHOTO 6: Area of impacted soil near prime mover engine skid. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



PHOTO 7: Area of impacted soil near prime mover engine skid. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



PHOTO 8: Area of impacted soil near compressor skid. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. ca date 2/23/2026.



PHOTO 9: trash on location near compressor skid. Remove all trash from on and around location per rule 606. ca date 2/23/2026.



PHOTO 10: trash on location near compressor skid. **Remove all trash from on and around location per rule 606. ca date 2/23/2026.**



PHOTO 11: OILY WASTE IN COMPRESSOR SKID WITHOUT WILDLIFE PROTECTION SCREENS OR COVERS. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. immediate action is required, ca date 2/11/2026.



Network: Feb 10, 2026 at 1:59:52 PM MST
Local: Feb 10, 2026 at 1:59:52 PM MST
+37.119446, -104.888465
Las Animas County

PHOTO 12: OILY WASTE IN PRIME MOVE ENGINE SKID WITHOUT WILDLIFE PROTECTION SCREENS OR COVERS. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. immediate action is required, ca date 2/11/2026.