

Inspection Photos

02/06/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334835

Inspection Doc: 719200805

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334835



Photo 1: Photos showing an overview of the location looking northwest and southeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334835



Photo 2: Photos showing an overview of the location looking southwest and northeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334835



Photo 3: Photos showing an overview of the southern interim area. Perennial grasses and shrubs are present and interim areas are well-established; interim areas are progressing towards 1003 reclamation standards.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334835



Photo 4: Photos showing a patch of Russian knapweed, a List B noxious weed species, is present in the southern interim area. Weed control is required; a follow-up inspection will be conducted during the 2026 growing season to evaluate weed control efforts at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334835



Photo 5: Photos showing erosion and rilling that has begun to occur on the northern edge of the working pad surface; maintenance is advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334835



Photo 6: Photos showing an example of prickly Russian thistle, an undesirable plant species, is present on the eastern edge of the working pad surface. Weed control is required; a follow-up inspection will be conducted during the 2026 growing season to evaluate weed control efforts at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334835



Photo 7: Photos showing examples of wellhead signage that is beginning to slip out of place; maintenance to secure signage in place is advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources