

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404541501

Date Received:
02/11/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>regulatory@logosresourcesllc.com</u>
<u>Blair, Jamie</u>		<u>steve.labowskie@state.co.us</u> <u>jamie.blair@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 721100095
Inspection Date: 02/02/2026 FIR Submit Date: 02/03/2026 FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC Company Number: 10679
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 324973

Location Name: NORTHWEST CEDAR HILL 32 Number: 20NWSW County: LA PLATA
-10-N32N10W
Qtrqr: NWS Sec: 20 Twp: 32N Range: 10W Meridian: N
W
Latitude: 37.002180 Longitude: -107.962240

FACILITY - API Number: 05-067- -00 Facility ID: 213754

Facility Name: NORTHWEST CEDAR HILL Number: 2-20
32-10
Qtrqr: NWS Sec: 20 Twp: 32N Range: 10W Meridian: N
W
Latitude: 37.002180 Longitude: -107.962240

CORRECTIVE ACTIONS:

1 CA# 210766

Corrective Action: Install sign to comply with 605.e. Date: 04/07/2026

Response: CA COMPLETED Date of Completion: 02/11/2026

Operator Comment: Well sign Emergency Contact Sticker Updated

ECMC Decision: _____

ECMC Representative: _____

2 CA# 210767

Corrective Action: Remove all dead vegetative debris a minimum of 25 feet from wellhead, tank and separator to comply with rule 610.k

Date: 02/06/2026

Response: CA COMPLETED

Date of Completion: 02/11/2026

Operator Comment: All dead vegetation cleaned up and latch on door

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Well sign updated and dead vegetation cleared around equipment

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Howell

Signed: _____

Title: Sr Staff Land Analyst

Date: 2/11/2026 11:04:37 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404541501	FIR RESOLUTION SUBMITTED
404541544	Vegetation Cleared
404541545	Vegetation Cleared
404541546	Vegetation Cleared
404541548	Vegetation Cleared
404541549	Vegetation Cleared
404541550	Latch to Door
404541551	Vegetation Cleared
404541552	Well Sign Fixed

Total Attach: 9 Files