

# Reclamation Inspection

January 30, 2026

Operator: NOBLE ENERGY INC - #100322

Location ID: 490053

Inspection Document #: 697506069

Weld County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Parcel T089  
Location ID: 490053



Jan 30, 2026 11:48:48  
ECMC Reclamation

**Photo 1.** Photo taken from CR51 and the western portion of Parcel T089 at the surface owners driveway, facing North. Photo illustrates the Operator excavated soil from the roadside ditch.



Jan 30, 2026 11:48:57  
ECMC Reclamation

**Photo 2.** Close up photo taken from Photo #1 illustrating that not all soil has been brought back to pre-disturbance conditions. Photo illustrates ~3-4 inches of soil material has not been brought back to the original contour.



Inspection Photos  
Location Name: Parcel T089  
Location ID: 490053



**Photo 3.** Photo taken from CR51 and the western portion of Parcel T089 near the surface owners driveway, facing East. Photo illustrates not all soil has been brought back to pre-disturbance conditions. Photo illustrates ~3-4 inches of soil material has not been brought back to the original contour.

