


Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118



01. Well Sign

Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118



02: Access road and well pad.

Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118




03. Access road.

Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118



04. Wellhead and cellar.

Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118



05. Bradenhead inside cellar.

Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118



**06. Wellhead and flowline. There is a produced water leak by the arrow coming from the pipe on the flow line blow-down. The leak has stained the soil beneath the flow line.**

Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118



07. Close-up of produced water drip.

Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118



09. Overview of pad looking southeast.

Inspection Photos  
Kinder Morgan – Goodman Point (GP) #25  
API # 05-83-06685  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #: 721100118



09. View of well pad from south end looking north.