

Inspection Photos

February 11th, 2026

Operator: Simcoe LLC

Location ID: 325399

Inspection Document #: 714003452

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Knight A 1E
Location ID: 325399

February 11, 2026
171° S



Photo 1. View of the active pad taken from the northern edge facing center.

Inspection Photos

Location Name: Knight A 1E

Location ID: 325399

February 11, 2026
87° E



Photo 2. Separator labels have deteriorated and are no longer legible.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

February 11, 2026
355° N



Photo 3. Label on meter shed has deteriorated and is no longer legible.



Inspection Photos

Location Name: Knight A 1E

Location ID: 325399

February 11, 2026
284° W



Photo 4. Wellhead assembly.



Inspection Photos

Location Name: Knight A 1E

Location ID: 325399

February 11, 2026
142° SE



Photo 5. View of interim reclamation area vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources