

Inspection Photos

February 11th, 2026

Operator: Simcoe LLC

Location ID: 326340

Inspection Document #: 714003452

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

February 11, 2026
273° W



Photo 1. View of the active pad taken from the eastern edge facing center.

Inspection Photos
Location Name: Knight C1
Location ID: 326340

February 11, 2026
212° SW



Photo 2. Large patch of weedy russian thistle debris observed on the active pad.

February 11, 2026
1° N



Photo 3. Label on separator equipment has deteriorated and is no longer legible.

February 11, 2026
194° S



Photo 4. Wellhead assembly.