

Final Reclamation Inspection

December 9, 2025

Operator: WRITER ET AL * HAROLD D.

Location ID: 395926

Inspection Document #: 720300086

Weld County, CO

Isaac Thibedeau & Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STATE-66N55W 36NWSE

Location ID: 395926

Jan 6, 2026 at 3:54:12 PM
+40.441169,-103.473807
348° N
Merino CO 80741
United States



Photo 1. Photo taken from the location facing north.

Jan 6, 2026 at 3:54:18 PM
+40.441169,-103.473807
83° E
Merino CO 80741
United States



Photo 2. Photo taken on location, facing east. Showing bare area and stunted vegetation.



Inspection Photos

Location Name: STATE-66N55W 36NWSE

Location ID: 395926

Jan 6, 2026 at 3:54:24 PM
+40.441149,-103.473805
172° S
Merino CO 80741
United States

Jan 6, 2026 at 3:54:37 PM
+40.441149,-103.473805
288° W
Merino CO 80741
United States



Photo 3. Photo taken from the location, facing south.

Photo 4. Photo taken from the location, facing west.

Inspection Photos

Location Name: STATE-66N55W 36NWSE

Location ID: 395926




Photo 5. Photo taken from the location, facing south. See comment under photo 2



Photo 6. Photo taken from the location facing east.



Inspection Photos

Location Name: STATE-66N55W 36NWSE

Location ID: 395926



Photo 5. Photo taken from location facing northeast showing depressed area with vegetation growth.

Photo 6. Photo taken from the location facing east showing depressed area with bare area.



Inspection Photos

Location Name: STATE-66N55W 36NWSE

Location ID: 395926



Photo 5. Photo taken from the location, facing north showing area with stunted vegetation growth.

