

Audit Photos


Location Name: QB ENERGY OPERATING LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 2/9/2026



Location Overview – Photo #02688



Location – Photo #02695

Audit Photos

Location Name: QB ENERGY OPERATING LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 2/9/2026



Location – Photo #02694




Location – Photo #02689

Audit Photos

Location Name: QB ENERGY OPERATING LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 2/9/2026



Location/No Labeling on PBV – Photo #02691



Location – Photo #02697

Audit Photos

Location Name: QB ENERGY OPERATING LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 2/9/2026



Location – Photo #02701



Unsecured Hatch/Wildlife Entry Hazard – Photo #02690

Audit Photos

Location Name: QB ENERGY OPERATING LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 2/9/2026



Open-Ended Line at Wellhead – Photo #02700



Open-Ended Vent on PBV – Photo #02692

Audit Photos

Location Name: QB ENERGY OPERATING LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 2/9/2026



Open-Ended Vent on PBV – Photo #02693



Corrosion on AST – Photo #02698