

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1841 Entrance to location



Photo # 1867 Location

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1842 Location



Photo # 1850 Location

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1852 Location



Photo # 1858 Location

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1864 Location



Photo # 1898 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC LAD #1 PAD

Location ID: 314380

Date: 02/9/2026



Photo # 1899 SE corner of location



Photo # 1900 SW corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC LAD #1 PAD

Location ID: 314380

Date: 02/9/2026



Photo # 1901 NW corner of location

Photo # 1902 NE corner of location

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1913 Location



Photo # 1925 Wellhead seal test using Additel 681AEx pressure gauge

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1855 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Photo # 1856 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Inspection/Audit Photos

Location: KT RESOURCES LLC LAD #1 PAD

Location ID: 314380

Date: 02/9/2026



Photo # 1879 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Photo # 1880 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1884 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Photo # 1886 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1887 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Photo # 1890 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1895 Weeds/undesirable plant species on location surrounding production equipment presents a potential fire hazard

Photo # 1868 Production tank label in disrepair/lacks required labeling/not in compliance with CECMC rules

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026




Photo # 1859 Label on chemical tank starting to become illegible

Photo # 1904 Debris

Inspection/Audit Photos
Location: KT RESOURCES LLC LAD #1 PAD
Location ID: 314380
Date: 02/9/2026



Photo # 1928 Debris