

Final Reclamation and Stormwater Inspection

February 5, 2026

Operator: KP KAUFFMAN COMPANY INC

Location ID: 482899

Location Name: 33-2N-68W NENE Tank Battery Loc/

Inspection Document #: 718601355

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: 33-2N-68W NENE Tank Battery
Loc/
Location ID: 482899



Photo 1. Looking west across the north part of the tank battery location. Meter shed and riser remains. Desirable perennial vegetation is present on the location. Undesirable weeds such as kochia are also present on the location.



Photo 2. An excavation was present on the north side of the meter shed. A flowline was exposed below ground. Excavation was fenced. Several flags and markers were present around the location at appear to mark flowlines.



Inspection Photos
Location Name: 33-2N-68W NENE Tank Battery
Loc/
Location ID: 482899



Photo 3. Looking south across the southern storage tank area. The large storage tank has been removed from the location. Pipe risers, pvc, and metal pipe remain on location.



Photo 4. Looking east across the tank/ flowline reiser area. PVC pipes are present. A depression is present in the tank area.



Inspection Photos
Location Name: 33-2N-68W NENE Tank Battery
Loc/
Location ID: 482899



Photo 5. Flowline risers at the tank battery.



Photo 6. It appears that boreholes are present and open south of the tank battery location.



Inspection Photos
Location Name: 33-2N-68W NENE Tank Battery
Loc/
Location ID: 482899



Photo 7. The electric utility mentioned in the previous inspection located near well API 123-08631 appears to have been removed.



Photo 8. Reference vegetation to the west of the tank battery location.

