

Final Reclamation and Stormwater Inspection

February 5, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 318193

Well Name: DUANE E. NELSON 41-33 (2-68) #1-X

Inspection Document #: 718601361

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUANE E. NELSON 41-33 (2-68)
#1-X
Location ID: 318193



Photo 1. Looking south across the tank battery and well location. No oil and gas equipment remain on the location. Desirable perennial vegetation appears to have reached 80% coverage of the surrounding reference area.



Photo 2. Looking east from the wellbore area. Desirable perennial vegetation appears to have reached 80% coverage of the reference area.



Inspection Photos
Location Name: DUANE E. NELSON 41-33 (2-68)
#1-X
Location ID: 318193



Photo 3. Looking north from the wellbore area. See photo 2 comments.



Photo 4. Looking west from the wellbore area. There is a prairie dog den in this area that has grazed vegetation. Desirable vegetation is present in this area and appears to have reached 80% coverage of the nearby reference area.

Inspection Photos

Location Name: DUANE E. NELSON 41-33 (2-68)

#1-X

Location ID: 318193



Photo 5. Looking south from the wellbore area. See photo 2 comments.



Photo 6. Looking north across the location from the south edge of the location. See photo 1 comments.



Inspection Photos
Location Name: DUANE E. NELSON 41-33 (2-68)
#1-X
Location ID: 318193



Photo 7. Reference vegetation to the east of the well location.

Inspection Photos
Location Name: DUANE E. NELSON 41-33 (2-68)
#1-X
Location ID: 318193



Photo 8. Historical aerial imagery taken 08/1971. The main access road (green arrows) appears to be preexisting to oil and gas. Red circle approximate location of well and tank battery.

