

Inspection Photos

February 11th, 2026

Operator: Simcoe LLC

Location ID: 333824

Inspection Document #: 714003464

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Snook B1
Location ID: 333824

February 11, 2026
294° NW



Photo 1. View of the active pad taken from the northern edge facing center.

Inspection Photos
Location Name: Snook B1
Location ID: 333824

February 11, 2026
234° SW



Photo 2. Patchy dead vegetation on the active pad.



February 11, 2026
122° SE



Photo 6. Erosion forming on the active pad.