

Inspection Photos

02/11/2026

Operator: QB Energy Operating LLC #10844

Location ID: 324066

Inspection Doc: 719200825

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324066



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324066



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324066



Photo 3: Photos showing an overview of the northwestern and northern interim areas, respectively. Cheatgrass (yellow arrow) and weedy annual species are present throughout.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324066



Photo 4: Photos showing cheatgrass (yellow arrow) is present around the margins of the working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324066



Photo 5: Photos showing an example of Russian knapweed, a List B noxious weed, that is present in tertiary amounts within the northern interim area. Weed management is required at the location; comply with Rule 606.c. and 1003.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324066



Photo 6: Photos showing an overview of the western interim area. Overall, interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324066



Photo 7: Photos showing an unmarked guy line anchor that is present in the northern interim area. Comply with Rule 1003.a.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources