

Inspection Photos

February 11th, 2026

Operator: Logos Operating

Location ID: 325235

Inspection Document #: 714003467

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Espinosa 1
Location ID: 325235

February 11, 2026
46° NE



Photo 1. View of the project area facing north. Note: pad remains and surface owner equipment is being stored.

February 11, 2026
303° NW



February 11, 2026
344° N



Photo 3. View of plugged well location. Pit remains with water and old piping reuipment.