

Inspection Photos

02/11/2026

Operator: QB Energy Operating LLC #10844

Location ID: 383131

Inspection Doc: 719200830

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 1: Photos showing an overview of the reclaimed access road leading to the location. The access road is progressing towards 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 2: Photos showing examples of cheatgrass patches that are present along the reclaimed access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 3: Photos showing an overview of the location looking north and south, respectively. Vegetation is sparse in some central areas of the location; these portions may need more time to develop.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 4: Photos showing an overview of the location looking east and west, respectively. Vegetation is sparse in some central areas of the location; these portions may need more time to develop.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 5: Photos showing an overview of the northwestern and northern portions of the location, respectively. Cheatgrass dominates these portions of the location. Ongoing weed management is required until the location receives a passing final inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 6: Photos showing an overview of the northern portions of the location. Cheatgrass dominates this portion of the location. Ongoing weed management is required until the location receives a passing final inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 7: Photos showing an overview of the southwestern and southeastern portions of the location, respectively. These portions of the location are progressing towards 1004 reclamation requirements. Cheatgrass is beginning to establish in some portions of the southern area.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 8: Photos showing an example of straw wattles that are present on the southern/southeastern portion of the location and appear to be in disrepair. Removal is required before the location receives a passing final reclamation inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 9: Photos showing trace amounts of Russian knapweed, a List B noxious weed species, is present on the southern portion of the location. Ongoing weed management is required until the location receives a passing final inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 383131



Photo 10: Photos showing an example of vegetation on the adjacent reference area during the dormant season.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources