

# INSPECTION PHOTOS

Well: COCK-A-DOODLE-DOO 44-27

API #: 05-071-08429

INSPECTION DOC #: 716301988

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 2/18/2026

County: Las Animas




PHOTO 2: WELL SIGN



PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.