

Inspection Photos
Location Name: UPRR 43 Pan Am B3
Location ID: 318639




Photo 1 Location.

Photo 2 Wellhead sign.

Inspection Photos
Location Name: UPRR 43 Pan Am B3
Location ID: 318639



Photo 3 Wellhead, BOP.



Photo 4 Circulation tanks.

Inspection Photos
Location Name: UPRR 43 Pan Am B3
Location ID: 318639



Photo 5 Rig pump, Rig.



Photo 6 Accumulator trailer, Rig.

Inspection Photos
Location Name: UPRR 43 Pan Am B3
Location ID: 318639



Photo 7 Location.



Photo 8 Rig floor, Pump jack.