

INSPECTION PHOTOS

Well: PIONEER 34-27 & TR

API #: 05-071-07617

INSPECTION DOC #: 716302000

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 2/19/2026

County: Las Animas



EVERGREEN

NATURAL RESOURCES LLC

PIONEER 34-27 TR

COC59968A

SW/SE Sec. 27 T32S R67W

.25 Mile N off CR 32.5

API # 05-071-7617

Emergency Number: 911
or (719) 846-7898

LAT: 37.22297 / LONG: -104.87164

ADVERTENCIA

EVERGREEN

NATURAL RESOURCES LLC

PIONEER 34-27 TR

COC59968A

API 05-071-08548-0000

SW SE SECTION 27-32S-67W

WDID 1911598 / PERMIT # 73090-F

EMERGENCY No. 911 or 719-846-7898 (24 Hrs)

Network: Feb 19, 2026 at 1:34:31 PM MST

Local: Feb 19, 2026 at 1:34:31 PM MST

+37.222899, -104.871368

35° NE

Las Animas County

Remark: Energy and Carbon Management

PHOTO 2: WELL SIGN



Network:Feb 19, 2026 at 1:30:14 PM MST
Local:Feb 19, 2026 at 1:30:14 PM MST
+37.222496,-104.871548
5° N
Las Animas County
Remark: Energy and Carbon Management

PHOTO 3: LOCATION.



Network: Feb 19, 2026 at 1:30:55 PM MST
Local: Feb 19, 2026 at 1:30:55 PM MST
+37.222835, -104.871686
266° W
Las Animas County
Remark: Energy and Carbon Management

PHOTO 4: WELLHEAD AND EQUIPMENT.



Network: Feb 19, 2026 at 1:33:14 PM MST
Local: Feb 19, 2026 at 1:33:14 PM MST
+37.222876, -104.871454
186° S
Las Animas County
Remark: Energy and Carbon Management

PHOTO 5: TR WELLHEAD AND EQUIPMENT.



Network: Feb 19, 2026 at 1:35:36 PM MST
Local: Feb 19, 2026 at 1:35:36 PM MST
+37.222934, -104.871300
53° NE
Las Animas County
Remark: Energy and Carbon Management

PHOTO 6: TRASH OFF THE NORTH SIDE OF LOCATION APPEARS TO BE INSULATION FROM SOUND WALLS. **REMOVE TRASH ON AND AROUND LOCATION PER RULE 606. CA DATE 2/25/2026.**



PHOTO 7: NO NFPA STICKER POSTED, NO CAPACITY POSTED AND CONTENTS IS PRODUCED WATER NOT NONE POTABLE WATER.
REMOVE OR COVER NONE POTABLE WATER STICKER AND POST TANK BATTERY SIGHS PER RULE 605. CA DATE 3/3/2026.



Network: Feb 19, 2026 at 1:34:08 PM MST
Local: Feb 19, 2026 at 1:34:08 PM MST
+37.222763, -104.871332
63° NE
Las Animas County
Remark: Energy and Carbon Management

PHOTO 8: HATCH ON TANK IS OPEN WITH NO BIRD PROTECTION. PLUMB 2" PIPE SO HATCH CAN BE CLOSED OR INSTALL BIRD PROTECTORS PER RULE 608. CA DATE 3/3/2026.