

Inspection Photos
Location Name: Bailey 31-12 TB
Location ID: 446941



Photo 1 Location entrance.

Photo 2 Tank battery location.

Inspection Photos
Location Name: Bailey 31-12 TB
Location ID: 446941



Photo 3 Tank battery.

Photo 4 Tank battery signs.

Inspection Photos
Location Name: Bailey 31-12 TB
Location ID: 446941



Photo 5 Tank battery.

Photo 6 Tank battery.

Inspection Photos
Location Name: Bailey 31-12 TB
Location ID: 446941



Photo 7 Tank battery.



Photo 8 Location.

Inspection Photos
Location Name: Bailey 31-12 TB
Location ID: 446941




Photo 9 ECD.

Photo 10 Gas Meter Run card indicates current calibration.

Inspection Photos
Location Name: Bailey 31-12 TB
Location ID: 446941



Photo 11 Horizontal Heated Separator & nitrogen tank.